DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493

Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.9/14.3,0.0/1.6

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-000849 Address: 333 Burma Road **Date Inspected:** 08-Nov-2007

City: Oakland, CA 94607

OSM Arrival Time: 600 **Project Name:** SAS Superstructure **OSM Departure Time:** 1530 Prime Contractor: American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes No Ye Yong Jun, Li Wen Sheng **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Oualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A **Approved Drawings:** Yes No N/A **Approved WPS:** Yes No **Delayed / Cancelled:** Yes N/A No

34-0006 **Bridge No: Component:** CalTrans mock up

Summary of Items Observed:

Caltrans Quality Assurance (QA) Inspector, Dan Hernandez was present to observe the fitup, welding and related activities associated with the fabricating of Caltrans Mock-ups 89.00 and 77.00 for the San Francisco Oakland Bay Self Anchored Suspension Bridge, at Zhenhua Port Machinery Company (ZPMC) facility on Changxing Island. **Item Description**

89M Diaphragm In Progress

Caltrans QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of fill passes on diaphragm web plate p138 to diaphragm plate SA13. The weld joint is a Partial Joint Penetration (PJP) double bevel T-joint in the 2G position. The approved welders Xu Wei #066253, Liu Guo Xuan #066279, Chen Ruyang # 066726 and Guo Dengyun were using approved welding procedure specification WPS-B-T-3312-TC-P5. Caltrans QA Inspector measured current welding parameters at approximately 242 amps, 22 volts and 135 millimeters per minute (mm/min) travel speed. Preheat and interpass temperatures were verified during welding activities. The preheat temperature prior to the start of welding measures more than 110 Celsius (230 degree Fahrenheit) but less than 232 Celsius (450 degrees Fahrenheit) during maximum interpass temperature verification. SMAW welding consumable is verified and identified as classification E9018 H4R Excalibur 4mm diameter. An electrode oven was observed by Caltrans QA Inspector in use during the welding process. ZPMC Quality Control (QC) Certified Welding Inspector (CWI) Mr. Ye Yong Jun and Bureau Veritas Inspector Mr. Li Gang were observed monitoring welding activities at the work station.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)



77M Flange Reinforcing Ring

In Progress

Caltrans QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of fill passes on SA274 Flange Reinforcement Ring splice weld of plate's p1086 to p1082. The weld joint is a Complete Joint Penetration (CJP) double bevel butt-joint in the 3G position. The approved welder Wang Bing #048696 was using approved welding procedure specification WPS-B-T-2233-B-U3-F. Caltrans QA Inspector measured current welding parameters at approximately 202 amps and 25.6 volts and 110 millimeters per minute (mm/min) travel speed. Preheat and interpass temperatures were verified during welding activities. The preheat temperature prior to the start of welding measures more than 110 Celsius (230 degree Fahrenheit) but less than 232 Celsius (450 degrees Fahrenheit) during maximum interpass temperature verification. FCAW welding consumable is verified and identified as Supercored 71H, classification E71T-1, diameter 1.4 mm (.055 inches). ZPMC Quality Control (QC) Certified Welding Inspector (CWI) Mr. Ye Yong Jun and Bureau Veritas Inspector Mr. Li Wen Sheng were observed monitoring welding activities at the work station.



Summary of Conversations:

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By: Hernandez,Dan Quality Assurance Inspector **Reviewed By:** Cuellar,Robert QA Reviewer